

Figure 1. Site Locations



Figure 21. Limantour Beach Marsh Existing Conditions Site Plan

nhc



Figure 24. Alternative 2 and Alternative 3: Limantour Beach Marsh Restoration Plan

nhc




Figure 3. Muddy Hollow Creek Existing Conditions Site Plan

nhc

ELEVATIONS BASED ON NPS 63F-161,
1963 EL. = 92.96 FEET, MSL DATUM.

ALTERNATIVE 1A - IMPACT AREA SUMMARY			
CHANNEL EROSION UPSTREAM OF DELTA	DEPOSITION ON RESEVOIR BOTTOM	DEPOSITION PAST THE DAM TO THE TIDAL MARSH	OTHER EXPOSED SOIL AREAS
0.6 ACRES	2 TO 3 ACRES	0.6 ACRES	7 TO 8 ACRES




Figure 7. Alternative 1A: Muddy Hollow Creek Restoration Site Plan - Erosion and Deposition Areas with Adaptive Management

nhc

Point Reyes National Seashore
Coastal Watershed Restoration Project

Coastal Watershed Restoration Program –
Geomorphic Restoration Project - Environmental Assessment
Figure 2.4

Coastal Watershed Project - Geomorphic Restoration Estero Trail Reroute Buffer







Figure 12. Glenbrook Crossing Existing Conditions Site Plan

nhc





Figure 15. Alternative 1: Glenbrook Crossing Restoration Site Plan - Channel Development

nhc






Figure 18. Alternative 2: Glenbrook Crossing Restoration Site Plan - Channel Development

nhc

Point Reyes National Seashore
Coastal Watershed Restoration Project

Coastal Watershed Restoration Program –
Geomorphic Restoration Project - Environmental Assessment
Figure 2.9